AMENDMENT NO. 4 JULY 2013
TO
IS 101(Part 5/Sec 2) : 1988 METHODS OF SAMPLING AND TESTS FOR PAINTS, VARNISHES AND RELATED PRODUCTS

PART 5 MECHANICAL TESTS

Section 2 Flexibility and Adhesion

(Third Revision)

(*Page* 7, *clause* **3.4.2.1**) — Insert the following sentence at the end of the existing:

'In case of tungsten carbide tips or ruby tips the same can be reused provided they are found to be smooth, hemispherical and free from contamination on examining it under 30 x magnification.'

(CHD 20)

Reprography Unit, BIS, New Delhi, India